

Name\_

Unit #\_\_\_\_\_

First

Upgrades and Services Available

Last

Rear Tail Light upgrade, Improves visibility while towing (due to the location above tow vehicle)



Normal Price: \$475 Rally Price: \$375

(Picture shows only one light but packages include both lights and can be installed at any height)

Pump assisted rear radiator coolant fill, for those hard to fill radiators.



Normal Price: \$213 Rally Price: \$175



## **Maintenance Items**

## **P-molding Install:**

Small Slide-Out (7 x 7) Normal price <u>\$456</u>	Rally special \$345
Medium Slide-Out (11x 7) Normal price \$562	Rally special \$425
Large Slide-Out (15 x 7) Normal price <u>\$632</u>	<b>Rally special \$500</b>
Extra –Large Slide out (20x 7) Normal price <u>\$712</u>	Rally special \$595

(One room per customer unless we have time for all requests)

**\*\***Black P-molding is currently used on **most RV's** slide out repairs. It is a new product and due to the color and the difference in the manufacturing process they expect this product to withstand the weather conditions better.

Spot Seal as needed (Remove old silicone where cracked, Roof, Side walls or any Exterior area)  $$42.5 (\frac{1}{2} \text{ Hr}) - $85 (1\text{Hr})$ Depending on time spent, and area sealed.

\* While working outdoors we will do our best to plan seal jobs while wind conditions are ideal, but we are not responsible for wind blowing dirt or debris in sealant.

Roof seal complete: includes sealant removal, new sealant, and labor. Normal Price: \$975-\$1300 Rally Price: \$825

Side Wall seal complete: includes sealant removal, new sealant, and labor. Normal Price: \$1200 Rally Price: \$925



Mail no later than February1, 2014 Prices are valid for 2014 Rally Only

Please come by our trailer for specials on items (too many items to list). If you would like a specific part, please call our parts department and let them know you are coming to the rally, and save the cost of shipping.

*Cash, Check, or CREDIT CARDS can be accepted *		
Total Cost work sheet		
Item Description		Cost
Roof Seal \$825		
Wall Seal \$925		
High Mount Tail Light \$375		
Coolant fill \$175		
P-molding		
Small Slide-Out (7 x 7)	\$345	
Medium Slide-Out (11x 7)	\$425	
Large Slide-Out (15 x 7)	\$500	
Extra –Large Slide out (20x 7)	\$595	
Spot Seal 1/2Hr \$42.5 / 1hr \$ 8	35	
Total		



## **Action RV Services**

All Action RV Service can be booked with Alfateers but will be billed and paid to Action RV.

<u>Water Heater Service</u>: 1 hour labor, plus parts cost. <u>Detail of service</u>: Clean PC board contacts, replace igniter probe, blow out heat chamber and replace ECO

Refer Service: 1 hour labor

<u>Detail of service</u>: Remove orifice and clean, check for fault codes, check all wires for loose connections, inspect door seal/gaskets for air leaks, blow out boiler tube.

<u>Furnace Service:</u> 1 hour labor <u>Detail of service:</u> Blow out heat chamber, squirrel cage, and clean contacts.

\*Price for parts will vary per service.

Action RV will be bringing stove, water heater, and refrigerator parts available for sale at rally.

